

Stun-Cuff Logger Software

Instructions

This software will run on the following: WIN 2000, NT, XP, & Vista.

The CD provided will install the software. Insert CD and wait for the install program to appear. Press or Click on the "Install" button and wait. A message should appear after a few seconds saying "Install Successful".

The install will create a folder "C:\Stun-Cuff". Inside this folder is the **Stun-Cuff.exe** program. Also in this folder will be any reports downloaded from stun-cuff units.

After the program has been installed, it is suggested that you create a shortcut to the program onto the PC desktop. This is accomplished by opening "My Computer", opening the "C" drive, and then right clicking on to the Stun-Cuff folder, and then choosing **Send To->Desktop (create shortcut)**.

To connect the unit to the computer using USB:

- remove the cover of the unit
- plug the usb cable into the Stun-Cuff unit
- Start the Stun-Cuff program.
- Plug the USB cable into the PC computer.
- The program should now say "Connected".

If this program has been previously installed, a new install will fail saying "Unable to copy file". Delete the folder and then reinstall it.

When running the program...

Information:

The unit requires a USB MICRO-B cable.

Storage capacity 2000 entries.

At one shock per day, 5 days a week, 50 weeks a year, the Stun-Cuff unit can hold up to 8 years of data.

Note that using the USB will drain the battery a little. Avoid keeping it connected for long periods of time.

The Logger will also drain the battery somewhat so it is advised that the unit be charged before use if stored for more than 100 days. If the battery go dead, the clock will have to be set. A general guideline is to keep the units charged and ready for use.